

# SCANNERSTATION

**YOU ARE IN CONTROL**

**System Requirements**

**March 1 st 2008**

**V1.1**

**© 2008 BuTel Software / ScannerMaster**

## ScannerStation Installation Requirements Server PC:

PC specifications for SERVER software (these are the minimum requirements):

### **SERVER PC with 1 SCANNER :**

- Intel Pentium 4, min. 2 GHz. Or AMD equivalent
- Windows XP / 2000
- 512 Mb RAM
- 40 GB harddisk
- Standard soundcard with Line input
- 10/100 Network card
- 17" LCD screen
- Mouse/keyboard
- 1x 1/8" male - 3 feet stereo audio cable
- 1 x RS232 port

**> If PC does not have a RS232 connector an optional Uniden USB1 cable must be purchased!**

### **SERVER PC with 2 SCANNERS :**

- Intel Pentium 4, min. 2 GHz. Or AMD equivalent
- Windows XP / 2000
- 512 Mb RAM
- 40 GB harddisk
- free PCI slot ( not PCI express!)
- 1 x M-Audio DELTA1010LT soundcard
- 10/100 Network card
- 17" LCD screen
- Mouse/keyboard
- 2 x adaptor cable stereo jack male <> 1/8 " male (3 feet)
- 2x free USB ports
- 2 x Uniden USB1 cable

### **GENERAL:**

- All scanners must be either Uniden BCT15 or Uniden BCD996T.
- All locations must have a full-time network connection. The faster the speed/bandwidth the better
- All locations must have antennas and coax cable mounted and connected.

> M-Audio information and dealers: [www.m-audio.com](http://www.m-audio.com)

### **SERVER PC with 3 SCANNERS :**

- Intel Pentium 4, min. 2 GHz. Or AMD equivalent
- Windows XP / 2000
- 512 Mb RAM
- 40 GB harddisk
- Free PCI slot ( not PCI express ! )
- 1 x M-Audio DELTA1010LT soundcard
- 10/100 Network card
- 17" LCD screen
- Mouse/keyboard
- 3 x adaptor cable stereo jack male <> 1/8 " male (3 feet)
- 3 free USB ports
- 3 Uniden USB1 cables

### **SERVER PC with 4 SCANNERS :**

- Intel Pentium 4, min. 2 GHz. Or AMD equivalent
- Windows XP / 2000
- 512 Mb RAM
- 40 GB harddisk
- Standard soundcard with Line input
- Free PCI slot ( not PCI express!)
- 1 x M-Audio DELTA1010LT soundcard
- 10/100 Network card
- 17" LCD screen
- Mouse/keyboard
- Special audio connection cable (contact ScannerMaster for details/wiring diagrams)
- 4 free USB ports
- 4 Uniden USB1 cables

### **GENERAL:**

- All scanners must be either Uniden BCT15 or Uniden BCD996T.
- All locations must have a full-time network connection. The faster the speed/bandwidth the better
- All locations must have antennas and coax cable mounted and connected.

> M-Audio information and dealers: [www.m-audio.com](http://www.m-audio.com)